

Going, Going, . . .

This aerial photo was taken by Phillip Conner a member of the Mitchell Field Committee on January 28, 2018. The tide was approaching low tide when the photo was taken. This shot gives a good overview of what is happening at Mitchell Field. On the land side of the operation, you can see the new construction road looping through the lower meadow. This road was constructed to haul the demolition material from the causeway up to the processing and storage area and then out to the Mitchell Field access road for removal from the site. The material processing area is in the middle of that road.



Taken 1-28-18 by Phillip Conner

On the water side of the operation, removal of the connecting pier between the causeway and the breasting platform is underway. The portion of the pier closest to the causeway was removed by Reed & Reed to allow for the creation of a transfer area to bring the demolition materials ashore. As this work was being done, much of the remaining section of the connecting pier collapsed – you can see it in the water in the photo. This was anticipated by Reed & Reed and they are now working to break up and remove the concrete deck and the steel piles that supported the deck.

MJE 2-6-18